MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_ 27 NR _ 4 N _

			Crenford COUNTY
DESCRIPTION	OF	CORNER	_1/4_Corner between_Sections 3 & 17
DESCRIPTION	OF	CORNER	MONUMENT 1" Pipe with 4" Brees cap,
WITTNESSES	то	CORNER	- 7" Jack Pine N-10-E - 119-Links
			_ 12"_Black_Cak = S 84_E115_Links
			_ 14"_Black Cak = S 45_W - 57 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner had been previously located and perpetuated by Marcas Schaaf, Registered Land Surveyor, from original B.T.'s.

Corner was placed and witnessed February 1, 1951.

SURVEYORS SEAL

SIGNED DATE 3/2/51 -