MAR 2 9 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN CRAWFORD COUNTY

		Also Act 345, PA 1990	RECORDED
For corners in			On app od Trod o k
Crawford	Located In:	Corner Code #	28 BEC 99 3:01 P.M.
(County) 1. Public Land Survey	T <u>28N</u> R <u>1</u> 1 T <u>27N</u> R <u>1</u> TR_		SANERA MOORE REGISTER OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, 5. Private Claims,	Recorded Plat		1 B C D E F G H I J K L 2 6 5 4 3 2 1 1
	LIBER	4 PAGE 66	3 4 7 8 9 10 12 12 5
I, <u>James L. Schwandt</u> , in a field survey on <u>May 14</u> , 19 <u>99</u> , do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4			nt 8 19 20 21 22 23 24 nd
and 5 above were in conform	nance with the rules of the M	the corner points mentioned in lines 3, lichigan Board of Land Surveyors or by numented, recovered, found as expresse	a 10 30 29 28 27 26 25
NOTE: Not more than 4 certificate.	corners, all in the same tow	n and range, may be recorded on th	is 12 31 32 33 34 35 36
Δ Description of origina	I monument and accessori	es and/or subsequent restoration:	

- 1.) Post set by James Mullett, D.S., 1839 Pine 3", N70°E, 44 links Pine 3", N45°W, 12 links
- 2.) Carlos Laguire (date unknown) Visited corner

CRAWFURD COUNTY

PEER GROUP APPROVAL

Marvin E. Myers, P.S. **County Surveyor**

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/2" pipe with Department of Conservation brass cap, 1.5' North of a red topped post No witnesses found

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1 1/2" pipe with Department of Conservation brass cap, 1.5' North if a red topped post and is accepted as a careful and faithful reestablishment of the position of the original corner.

Spike in 12" Pine, S11°W, 126.55' Spike in 14" Pine, S44°W, 146.14' Spike in 10" Pine, N70°E, 101.80' Spike in 8" Pine, N6°E, 157.02'

JAMES L SCHWANDT PROFESSIONAL No. 26466 POFESSION Date

12-10-99

Signed by

higan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, REVISED MAY 14, REVISED JAN., REVISED OCT..