

CRAWFORD COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
COUNTY OF CRAWFORD

For corners in

Crawford (County)	Located In:	Corner Code #
1. Public Land Survey	T 28N R 1W	M-13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

FILED FOR RECORD THIS  
6<sup>th</sup> DAY OF Dec, 1993 AT  
3:20 am/pm, IN LIBER 3 4c  
PAGE 100

*Elizabeth D. Wieland*  
Register of Deeds

Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Marvin E. Myers, in a field survey on November 22, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

GLO - 1839 James H. Mullett DNR - July 1970 K. Ostling  
Mon. - Post Mon. - Std. Dept. Mon.  
WIT: 8" Spruce N75°W 28 lks. WIT: none given  
10" Cedar S10°W 39 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Dept. of Conservation Monument verified position by measurement to accessories and corners of record and accepted as the best available evidence of the re-establishment of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon. - Left in place Std. Dept. of Conservation Mon.  
WIT: nail & tag SE 6" J. Pine N36°E 66.22'  
nail & tag S. 5" J. Pine S78°E 25.92'  
nail & tag W. 6" Poplar S12°W 77.72'  
nail & tag S. 3" J. Pine S66°W 54.00'



Signed by Marvin E. Myers Date DEC 4, 1993

Surveyor's Michigan License No. 31600

DATE NOV 29, 1993 PEER GROUP APPROVAL