

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 NR. 1 W.

----- Crawford ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 8, 9, 16, 17 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 9" Cedar = N 5 W = 3/4 Links -----

8" Cedar = S 95 E = 1 1/2 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by double proportionate measurement, by Forestry Division survey crew, while making a partial resurvey of this Township. Two possible original B.T.s still in place, badly rotted.

Corner was placed and witnessed October 16, 1952.

SURVEYORS SEAL

SIGNED Shen C. J. Miller DATE 2/20/53
REGISTERED LAND SURVEYOR