

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 . NR. 1 . W. .

----- Crawford ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 1,2,11,12 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER -----

8" Cedar - S 85 E - 18 Links -----

12" Cedar - N 50 W - 23 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Two original B.T.'s still in place, in fair condition.

Corner was placed and witnessed June 8, 1953.

SURVEYORS SEAL

SIGNED James C. DeLoe
REGISTERED LAND SURVEYOR

DATE 2/8/54 -----