

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 NR. 1 E.  
T 28 NR 1 W

----- Crawford - Osceola COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 30 & 25 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER -----

9" Tamarack - West - 43 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located and perpetuated by Marcus Schaaf, Registered Land Surveyor. One original B.T. still in place, in poor condition.

Corner was placed and witnessed July 3, 1953.

SURVEYORS SEAL

SIGNED James C. DeBorja DATE 2/9/54  
REGISTERED LAND SURVEYOR