

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 27 NR 1 W
T 28 NR 1 E
T 28 NR 1 W

----- Crawford - Osceola ----- COUNTY

DESCRIPTION OF CORNER ~~Section Corner common to Sections 1, 31, 36~~ -----

DESCRIPTION OF CORNER MONUMENT ~~1" Pipe with 4" Brass cap~~ -----

WITNESSES TO CORNER -----

~~10" Tamarack - N 10 W - 96 Links~~ -----

~~18" Cedar Stub - S 45 E - 47 Links~~ -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located and perpetuated by Marcus Schaaf, Registered Land Surveyor. One original B.T. still in place, in fair condition.

Corner was placed and witnessed August 17, 1953.

SURVEYORS SEAL

SIGNED *Alan C. Schaefer* DATE 2/8/54
REGISTERED LAND SURVEYOR