

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 NR. 1 E.  
R. 28 N. R. 1 W.

----- Crawford - Osceola ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 30, 31, 36 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER -----

6" J. Pine - S 85 E - 9 Links -----

8" J. Pine - S 89 E - 10 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew, while making a partial resurvey of this area. Corner was placed 23 Links South of Corner for 30, 25, 36, as per Gov't. field notes.

Corner was placed and witnessed July 3, 1953.

SURVEYORS SEAL

SIGNED Dean C. DeLoe DATE 2/25/54  
REGISTERED LAND SURVEYOR