

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 NR. 1 E.
T. 24 N R 1 W

Crawford - Oscoda COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 6,7,12

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER

10" Balsam - S 55 W - 102 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously set by unknown Surveyor. Stream checks e.k. to the South, as per Government Notes. Corner is 101 Links South of Corner common to 1,12,6, as per Gov't. notes.

Corner placed and witnessed May 15, 1953.

SURVEYORS SEAL

SIGNED *Alan C. [Signature]* DATE 2/5/54
REGISTERED LAND SURVEYOR