

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 NR. 1 E.
T. 28 N. R. 1 W.

Crawford - Oscoda COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 19, 24, 25

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER

10" J. Pine - N 28 W - 32 Links

10" J. Pine - S 50 W - 62 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located and perpetuated by Marcus Schaaf, Registered Land Surveyor. Stump of one original B.T. still in place, in poor condition.

Corner was placed and witnessed July 3, 1953.

SURVEYORS SEAL

SIGNED *Dean C. DeLoater* DATE 2/9/54
REGISTERED LAND SURVEYOR