MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_27 NR_1 W.

	Grawford COUNTY
DESCRIPTION OF CORNERBectien Corner countr	to Sections 35, 36,1,2
DESCRIPTION OF CORNER MONUMENT_3/4" Pipe -	
WITTNESSES TO CORNER	
_ 10F_J. Pine = N 6 F = S	95_Idnks_
_ 10 % J. Pine = 8 28 F. m.	48 Idnes

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by double proportionate measurement, by Forestry Division survey crew, while making a pertial resurvey of this area. Corner lies in approximate centerline of read.

Corner was placed and witnessed July 3, 1953.

SURVEYORS SEAL

SIGNED SIGNED LAND SURVEYOR DATE 2/25/54