

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28. NR. 1. E.
T. 28. NR. 1. W.

Crawford - Osceola COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 18,19,24

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER _____

20" Red Pine - 8.73 E = 84 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located by Marcus Schaaf, Registered Land Surveyor. Corner is 85 Links South of Corner common to 18,19,24.

Corner was placed and witnessed April 9, 1953.

SURVEYORS SEAL

SIGNED Dean C. DeLoe DATE 2/5/54
REGISTERED LAND SURVEYOR