

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28. NR. 1. W.

Grayford COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 11, 12, 13, 14

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER

9" J. Pine - S 40 E - 30 Links

8" J. Pine - N 55 E - 33 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Stream crossings East, West and South check o.k.. Two probable original B.T.'s still in place, in poor condition.

Corner was placed and witnessed April 3, 1953.

SURVEYORS SEAL

SIGNED Dean C. DeBate DATE 2/8/54
REGISTERED LAND SURVEYOR