

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 28 NR. 1 W.

Crawford COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 13 & 14

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER

12" J. Pine - N 68° E - 70 Links

9" J. Pine - N 25° E - 80 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew, while making a partial resurvey of this Township. In the absence of any original evidence, the corner was placed in line, and at a proportionate distance between the two Section Corners.

Corner was placed and witnessed April 7, 1953.

SURVEYORS SEAL

SIGNED Alan C. DeMa DATE 2/3/54
REGISTERED LAND SURVEYOR