

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 20 NR 2 W  
T 20 NR 2 W

Crawford - Otsego COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 5, 6, 31, 32

DESCRIPTION OF CORNER MONUMENT 1/2" Peg encased in 4" concrete monument

WITNESSES TO CORNER No witness trees available

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located and perpetuated by G. F. DeLaWater, Registered Land Surveyor, of Gaylord.

Corner was found and noted November 12, 1952.

SURVEYORS SEAL

SIGNED *G. F. DeLaWater*  
REGISTERED LAND SURVEYOR

DATE 9/20/53 -