STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

LAND CORNER RECORD

			CRAWFORD		COUNTY		
		Τ.	28	N	R _	3	W
DESCRIPTION OF CORNER	1/4 corner common to Secti	ons 3 -	- 10			 	
CORNER MONUMENT	Set Department Monument be	low roa	ıd sur	face			
DATE MONUMENT PLACED AND	WITNESSED6-19-70						
WITNESSES TO CORNER							
N	6" Cherry	N 40) <u>E</u>		74.7	2'	
10	48"x12' W. Pine Stub	S 10) E		75.0)'	
	AND						
CIRCLE CORNER REGISTE	RED						

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement during a survey in this township. Unable to locate anything for a previous corner. The U.S. record makes this mile a straight line, although a pre 1900 road survey would appear to inject a substantial deflection at this corner, placing it South of the road. Felt bound to honor U.S. record without conclusive evidence to the contrary.

SURVEYOR'S SEAL

DISTRIBUTION: