

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

CRAWFORD COUNTY


T 28 N R 3 W

DESCRIPTION OF CORNER 1/4 corner common to Sections 17 - 18

CORNER MONUMENT Set Dept. Monument beside 1/2" pipe

DATE MONUMENT PLACED AND WITNESSED 6-19-70

WITNESSES TO CORNER..... 6" H. Maple N 87 W 50.2'



7" J. Pine N 68 E 53.4'

Boat Spike N 80 W 4.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Found 1/2" pipe in road, origin unknown, but seems to fit a proper pattern of survey for this area. The boat spike was likely a traverse point left from MSHD survey.

SURVEYOR'S SEAL

SIGNED

Levitt Ostling

DATE 7-7-70

REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68