STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		CRAWFO	<u>COUNTY</u>
		T <u>28</u>	N R 3 W
DESCRIPTION OF CORNER	1/4 corner common to S	ections 20-29	
CORNER MONUMENT	Set Department Monumen	t below road stu	rface
DATE MONUMENT PLACED AN	D WITNESSED6-19-	70	
VITNESSES TO CORNER	••		
N	8" H. Maple	N 27 E	53.11
20	8" Tw. H. Maple	S 23 E	40.2'
	AND		
CIRCLE CORNER REGISTI	ERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored during a retracement in this township. Set corner from probable Newman witnesses, as recorded in early 1900 survey. Two stumps in place and possible evidence of stake remains. Also falls in line with fence North and 33' S. of fence corner.

SURVEYOR'S SEAL

SIGNE

ENED LECCEPTE CAND SURVEYOR ADORS

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing