## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		CRAWFORD	COUNTY
		T <u>28 N</u>	R <u>3 W</u>
DESCRIPTION OF CORNER _	1/4 corner common	to Sections 29 - 30	
CORNER MONUMENT	Left Conc. tile in	place	
DATE MONUMENT PLACED AND I	MITNESSED 6-19-	70	
WITNESSES TO CORNER			
N	5" H. Maple	N 65 E	56.7'
p 29	5" H. Maple	S 23 E	83,7'
	AND		
CIRCLE CORNER REGISTERS	D		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Houghton tile at corner, in line with fence West and center of N-S road. Apparently of long standing and locally accepted.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED REGISTERED LAND SURVEYOR 10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing