## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		CRAWFORD	
		T <u>28 N</u>	
DESCRIPTION OF CORNERC_	1/4 corner common to Se	ection 8	
CORNER MONUMENTSet	Dept. Monument		
DATE MONUMENT PLACED AND WITNE	SSED <u>6-26-70</u>		
WITNESSES TO CORNER	8" Beech	S 69 E	7.31
Sec. 8  Ctr	12" Beech	N 05 E	29.7'
Post	1/2" W. Pine	N 05 E	4.71
AND			
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set at intersection of N-S & E-W 1/4 lines, to identify state ownership in Section 8. A previous survey erroneously established this corner, without proper control on boundary of section.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED LECCE STATE 7-17-70

REGISTERED LAND SURVEYOR#19068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing