## STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

## LAND CORNER RECORD

	Otsego <u>Crawford</u>	COUNTY
	T <u>28 &amp; 29</u>	R3W
DESCRIPTION OF CORNER 1/4 corner common to	o Sections 33 - 4	
CORNER MONUMENT Set Dept. Monument		
DATE MONUMENT PLACED AND WITNESSED6-26-70		
WITNESSES TO CORNER	······································	
N16" Maple	S 74 E	9.81
<u>-</u>	N 9 E	8.7'
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement, midpoint on line, between section corners. Falls in line with 1/4 line fence North and 24' S of fence corner.

SURVEYOR'S SEAL

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing