STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		_	CRAWFORD		COUNTY		
		T	28	N	R _	3	W
DESCRIPTION OF CORNER	1/4 corner common to Sections	8	- 17				
CORNER MONUMENT	Department Monument						
DATE MONUMENT PLACED AND WI	NESSED <u>6-19-70</u>						
WITNESSES TO CORNER						-	
N -	32" W.P. Stump		S_6	5_E_		 16	.3'_
 	10" Maple		S_2	2 W		61	.41
A	1/2" Re-Rod		<u>N 1</u>	3 E		27	.7'
CIRCLE CORNER REGISTERED							

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement, and in conformity with the U.S. record for alignment, during a survey in this area.

A 1/2" iron bar was apparently established in a survey of the SW 1/4 without sufficient information on section control, and was disregarded in favor of a proportionate restoration. No U.S. evidence.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR 10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing