## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		CRAWFORD	COUNTY
		T <u>28 N</u> R	3 W
DESCRIPTION OF CORNER _	1/4 corner common to Sect	ions 7 - 8	
CORNER MONUMENT	Set Dept. Monument		<del></del>
DATE MONUMENT PLACED AND	WITNESSED 6-19-70		
WITNESSES TO CORNER			
N	12" Maple	N 65 E	34.9'
6	8" Maple	S 33 E	47.1'
	AND		
CIRCLE CORNER REGISTER	ED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Found a 10" cabin spike in center N-S road at distance prescribed by County Surveyor Houghton record, with a concrete monument 33' East. Best available evidence of corner.

SURVEYOR'S SEAL

SIGNED

maragener was supressed

LON

REGISTERED LAND SURVEYOR 1006

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing