

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


CRAWFORD COUNTY  
T 28 N R 3 W

DESCRIPTION OF CORNER 1/4 corner common to Sections 19 - 20

CORNER MONUMENT 1/2" Sq. Iron rod in Concrete filled tile

DATE MONUMENT PLACED AND WITNESSED 6-19-70

WITNESSES TO CORNER.....



8" Hard Maple N 77 E 45.5'

Triple 6" Ironwood N 40 W 72.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Corner previously established by County Surveyor Houghton by unknown methods. Appears to be the best available evidence of proper location for corner. In centerline of N-S road.

SURVEYOR'S SEAL

SIGNED *Walter J. Osting* DATE 7-17-70  
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68