STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

| | | | CRAWFURD | | | COUNTY | | |
|--------------------------|----------------|----------------------|----------|----------|-----|--------------|------------|--|
| | | Τ . | 28 | <u> </u> | R. | 3 | W | |
| DESCRIPTION OF CORNER | Sec. corner co | numon to Secs. 7- | 8-17- | 18 | | | | |
| CORNER MONUMENT | 1/2" Square i | ron in concrete f | illed | tile | in | place | L . | |
| DATE MONUMENT PLACED ANI | WITNESSED | Found J | en. 1 | 970 | | | - | |
| WITNESSES TO CORNER | . 12" Maple | 8 63 R | | | _40 | .25 <u>'</u> | | |
| N | 8" Maple | 8 63 W | | | 31 | <u>.61'</u> | | |
| 17 | 12" Naple | N 58 W | | | 47 | .54' | | |
| | AND | IDSH WITHESES | | | | | | |
| CIRCLE CORNER REGISTE | RED | | - | | | | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by M.D.S.H. during I-75 survey, December 1957. Set by E. Houghton.

SURVEYOR'S SEAL

GNED ELLE LELL SURVEYOR 10068

8-20-70

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68