## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## L'AND CORNER RECORD

			_ <u>C</u>	CRAWFORD			COUNTY		
			T	28	<u>N</u> _	Ř.	3	W	
DESCRIPTION OF CORNER	Center 1/4	corner common	to Section	s 9 0	nly			,	
CORNER MONUMENT	Set 1-3/4"	pipe in block	of concret	е					
DATE MONUMENT PLACED AND	WITNESSED	2-2	22-71						
WITNESSES TO CORNER	•								
Sec. 9	8"	Maple	N 46 W			23	3.25		
	10"	Beech	S 27 W			25	.9'		
	AND								
CIRCLE CORNER REGISTER	ED						<del></del> -		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set at the intersection of the N-S & E-Walines

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR DAT

3-2-71

10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047 Rev. 10/68