STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

					CRAWFORD			COUNTY		
				T	28	1	N	R _	3	W
DESCRIPTION OF CORNER Se	ec. corne	er rommon to	Sections	. 4-	-5-8-9					
CORNER MONUMENTSe	et Dept.	Monument								
DATE MONUMENT PLACED AND WITH	NESSED	5-14-70	<u> </u>							
WITNESSES TO CORNER	<u> </u>	33" W. Pine	Stp		S	09	W			79.6'
N -	<u>-</u>	10" Poplar			S	48	W			22.8'
4		24" W. Pine	Stp		N	39	E			8.3!
ANI	D									
CIRCLE CORNER REGISTERED										

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by double proportionate measurement between corners one mile North, East, West and 1/2 mile South, during a survey in this area. Unable to locate anything for a previous corner. No conclusive evidence.

SURVEYOR'S SEAL

SIGNED 4

Z DATE 7-17-70

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047 Rev. 10/68