## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

			CRAWFORD		COUNTY		
		T	_28	N	R	3	W
DESCRIPTION OF CORNER	1/4 corner common to Section	s 28	- 29		· · · · · ·	-	
CORNER MONUMENT	Set Dept. Monument						
	D WITNESSED 5-15-70						
WITNESSES TO CORNER	••						
N	9" W. Pine		S	62 W		69	.6'
028	7" W. Pine		N.	71 W		71	41
	AND						
CIRCLE CORNER REGISTE	ERED						

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established during a survey in this area. Set corner in line with fence East and 33' from fence corner, which very nearly conforms to #.L.O. record and old County road survey measurements. Any previous corner apparently removed, but this position appears to be best available evidence of proper location for corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED EMELLA SILLIA DATE 7-15-70
REGISTERED LAND SURVEYOR 10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing