

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


CRAWFORD COUNTY
T 28 N R 3 W

DESCRIPTION OF CORNER 1/4 corner common to Sections 29 - 32

CORNER MONUMENT Left 1/2" iron bar in place 4' S of Center of Road

DATE MONUMENT PLACED AND WITNESSED 5-15-70

WITNESSES TO CORNER..... 12" Apple S 72 W 102.0'



West Gate Post N 72 E 105.6'

W end CMP Culvert S 24 W 23.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this area. Previously established and perpetuated in early survey by local surveyors.

SURVEYOR'S SEAL

SIGNED

Anneth Estline
REGISTERED LAND SURVEYOR #10068

DATE 7-15-70

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68