

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

CRAWFORD COUNTY


T 28 N R 3 W

DESCRIPTION OF CORNER Sec. corner common to Secs. 28-29-32-33

CORNER MONUMENT Left 5/8" rod in place, raised with 10" cabin spike

DATE MONUMENT PLACED AND WITNESSED 5-15-70

WITNESSES TO CORNER..... Power Pole S 46 E 51.8'



Corner fence post N 46 E 46.9'

2 - 6" R. Pines N 48 W 88.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Probably established in alignment survey for County Road 612.

SURVEYOR'S SEAL

SIGNED

*Robert J. DeLong*

DATE

7-15-70

DISTRIBUTION:

REGISTERED LAND SURVEYOR 10068

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68