## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		CRAWFORD			COUNTY		
	Т	_28	N	_ R	3	W	
DESCRIPTION OF CORNER <u>Section corner common to Sec</u>	ctio	ns 20-	21-:	28 <b>–2</b> 9			
CORNER MONUMENTLeft 1½" pipe in place		_				<del></del> ·	
DATE MONUMENT PLACED AND WITNESSED							
WITNESSES TO CORNER							
N Power Pole		N	60	E	71	.81	
Tele. Junction Box	c Pos	st S	32	<u>E</u>	67	.3'	
AND							
CIRCLE CORNER REGISTERED							

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Previously established in early local survey by County Surveyor.

Falls about 3' West of Center of N-S road and 7' North of Centerline of road East.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED REGISTERED LAND SURVEYOR 10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing