## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		CRAWFORD	COUNTY
	Т	28 N	R _ 3 W
DESCRIPTION OF CORNER Sec. com	rner common to Sections 3	-4-9-10	
CORNER MONUMENT Sq. Head	d Bolt		
DATE MONUMENT PLACED AND WITNESS	ED <u>5-14-70</u>		
WITNESSES TO CORNER	R. Pine	S 86 W	59.7'
N	Power Pole	N 37 E	54.51
	Centerline Pay't	West	3.81
AND			
CIRCLE CORNER REGISTERED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set during a survey in this township. Established corner at center-line intersection of N-S.E roads. Unable to locate a previous corner in deep fill section. Bolt placed at our location by Norm Parker, R.L.S. in a local survey.

Best evidence of corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED LECELO LAND SURVEYOR 10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing