

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 24. NR. 3. W.
R. 29. N. R. 3. W.

----- Crawford - Osage - COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 1, 2, 35, 36. -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 20" W. Pine Stump - N 44 W - 24 Links -----

30" W. Pine Stump - S 10 E - 40 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located and perpetuated by G. W. DeLaMater, Registered Land Surveyor, of Gaylord.

Corner was placed and witnessed November 12, 1952.

SURVEYORS SEAL

SIGNED John C. DeLaMater DATE 2/20/53
REGISTERED LAND SURVEYOR