

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

CRAWFORD COUNTY


T 28 R 3 W

DESCRIPTION OF CORNER Sec. corner common to Sections 16-17-20-21

CORNER MONUMENT Left RR iron in place

DATE MONUMENT PLACED AND WITNESSED 5-7-70

WITNESSES TO CORNER.....



32" Maple N 55 W 51.0

23" Maple S 81 W 54.9

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a retracement in this township. Found RR iron of long standing and acceptance at corner, as established in early local survey. Best evidence of proper location of corner.

SURVEYOR'S SEAL

SIGNED *Kenneth R. Estling* DATE 7-7-70  
REGISTERED LAND SURVEYOR 10068

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68