STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

			CRAWFORD			COUNTY	
		Τ_	28	N	R _	3	W
DESCRIPTION OF CORNER	Sec. corner common to Sec	ctions 10-	-11-14	-15			
CORNER MONUMENT	Set Dept. Monument						
DATE MONUMENT PLACED AND	WITNESSED 5-26-70						
WITNESSES TO CORNER	•	.			. <u> </u>		
N		-	o.(==		0.4		
)	24" W. Pine Stp	S	24 E		84	4.4	
10	Cor. Fe Post	We	st		33	3.0_	
	AND						
CIRCLE CORNER REGISTER	ED						<u>_</u>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored during a survey in this township. Set this corner in line with an old fence line West between 10-15, and 33' E of fence corner. This point falls near center of old N-S road grade. Nothing could be located for a previous corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED CILLLE LAND SURVEYOR 10068

7-7-70

REGISTERED LAND SURVEYOR 10068

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing