


STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD

CRAWFORD COUNTY
T 28 N R 4 W

DESCRIPTION OF CORNER NW corner Sec. 22
CORNER MONUMENT Left 1" Axle shaft in place
DATE MONUMENT PLACED AND WITNESSED 5-3-72
WITNESSES TO CORNER.....



8" Basswood S 55 E 44.8'
14" H. Maple S 63 W 62.2'
AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 1" axle shaft in place in center of N-S road, in line with fence West. Set by unknown, but appears acceptable as the proper location for corner.



DISTRIBUTION:

SIGNED

Kenneth J. Ostling
REGISTERED LAND SURVEYOR
10068

DATE

5-24-72

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68