## STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

## LAND CORNER RECORD

DESCRIPTION OF CORNER S 1/4 corner, Section 26  CORNER MONUMENT 5/8" Iron Bar  DATE MONUMENT PLACED AND WITNESSED 5-25-72  WITNESSES TO CORNER						
CORNER MONUMENT 5/8" Iron Bar  DATE MONUMENT PLACED AND WITNESSED 5-25-72  WITNESSES TO CORNER					<del></del>	
DATE MONUMENT PLACED AND WITNESSED						
VITNESSES TO CORNER						
					· <u></u>	
6" W. Pine						
6" Balsam		N 18	W		77.	6.
AND						
CIRCLE CORNER REGISTERED						
DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND I	DEN	NTIFIE	D OR	RES	TORE	D.

in the SW 1/4 of Sec. 26, although Henning 1950 survey used a theoretical midpoint some 21' West of pipe. Feel the iron is best evidence of proper position for this corner.

KENNETH J. OSTLING LAND SURVEYOR SURVEYOR SURVEYOR CAND SURVEYOR
DISTRIBUTION:

REGISTERED LAND SURVEYOR 10068

Forestry Division, Lansing

F	٤ ،	404	7	
F	le,	v.	1/	72