STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		<u>CRAWFORD</u> COUNTY					
		τ_	28	<u> </u>	R.	_4	W
DESCRIPTION OF CORNER	SW Corner, Sec. 26						.
CORNER MONUMENT	Left l" pipe in place						<u></u>
DATE MONUMENT PLACED AND WI	TNESSED	5-23-72	2				<u>_</u>
WITNESSES TO CORNER	15" Tamarack	N 22 E	<u>.</u>			LO3.4	5'
N	10" Tamarack	<u>s 43 e</u>			. 	90.0	<u> </u>
26	NE cor. Conc. Blk House	S 56 W				78.7	•
	AND (Renewed Henning	NBTs)					
CIRCLE CORNER REGISTERED)		· ·				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found corner as placed by unknown but found acceptable in subsequent surveys by DeLaMater and Henning and others.

ينور	KENNETU	
***************************************	L OSTROLO	0277 ***
and the state of t		SEAL
	DISTRIBUTIO	N:

SIGNED REGISTERED LAND SURVEYOR DATE

5-25-7

10068

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing