

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

CRAWFORD COUNTY


T 28 N R 4 W

DESCRIPTION OF CORNER West 1/4 corner, Sec. 26

CORNER MONUMENT Left 1/2" iron bar in place

DATE MONUMENT PLACED AND WITNESSED 5-23-72

WITNESSES TO CORNER..... \* 10" Cedar S 62 W 43.1'



\* 11" Cedar N 65 W 43.2'

\* Henning's NBTs renewed.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found 1/2" iron bar at corner which was intended to restore Henning's 1950 corner.  
This approximate position used in the subdivision of Sec. 26 and more recent control  
for the N 1/16 between 26 & 27.



DISTRIBUTION:

SIGNED Kenneth J. Ostling DATE 5-25-72  
REGISTERED LAND SURVEYOR 10068

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68