MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_23 NR_4.W__

		Cremford COUNTY
DESCRIPTION	OF CORNER	R 1/4 Corner between Sections 7 & 3
DESCRIPTION	OF CORNER	MONUMENT_1 Pips_with At Erras cap
WITTNESSES	TO CORNER	10" S. Heple - S.60 N - 123 Links
		_ 10" S. Maple = N 18 E = 101 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Corner had been previously located and perpetuated by Marcus Schaaf, Registered Land Surveyor.

Corner was placed and witnessed December 13, 1951.

SURVEYORS SEAL

SIGNED SEAR LAND SURVEYOR DATE 1/18/52