MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T__23. NR__4_#_

			Cressford COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner-between Sections-17 & 13
DESCRIPTION	OF	CORNER	MONUMENT_1E Pipe with 4E Brees cap
WIT TNESSES	то	CORNER	_ 15*_Ecd Cak = S -54 E 80-Links
			_ 15 Red_Cak = S 48_W_=_76 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Corner had been previously located and perpetuated by Marous Schaaf, Registered Land Surveyor.

Corner was placed and witnessed December 13, 1951.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 1/13/52