## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

			L 11	iiiy K	equi	remen	It OF ACI	1 74, WIICH	   	197	U							
For Corners In: Crawford		Located In			Corner Code #													
(County)																		
Public Land Survey		T T		R														
Property Controlling in Section	S 35	T - T	28N	- R	1W		3											
Miscellaneous     Property in Section	s	- ' _ T		R														
	S	Т		_ R_							Regi	ster	of De	eds S	tamp	& Fi	le Nun	nber
4. Lot No:	Recorde	ed Plat: A B C D E F G H 1 J K														ΚĿ	м	
5. Private Claims:										— e	_	· 5 —	  4-		3	_   ² _	<u> </u>	
I, <u>Carl T. Kiiskila,</u> in a field survey on <u>April 17, 2003</u> do hereby state that under							3	-		+				_	11	$\dashv$		
requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1						4	7		8	9 –	+	10	11	12.	$\dashv$			
and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules							5			<del> </del>			<u>†</u> +		† †			
							7							_14-				
of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:								8	19	,	20		$\perp$	22	- 23 <b>-</b> -	24		
									9			-		+		$\perp$		
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.									10	—3 <sup>1</sup>	<b>-</b>	-29 	28-	+	27	—2 <mark>6</mark> -	25	
									11			-			+		+	$\dashv$
									12 13			32—	33-		34	-€35-	36	
A. Description of original							sequen	t restoratio	n:									
<ul> <li>8- This corner position original government se</li> </ul>		est	ablishe	d duri	ing ti	he												4
onginal government s	urvey.																	
B. Description of corner	evidence	four	d and/o	r meth	od a	pplies i	in restor	ing or re-e	stabli	shin	g cor	ner:						
8- Established the No	rthwest c	orn	er of the	e Nor	hea	st qua	rter											
of the Southwest quar					I.L.N	1.												
instructions for the su	baivision	or a	sectio	n.														
•																		
C. Description of monun	nent for co	rne	and ac	cesso	ries e	establis	shed to p	perpetuate	locat	ing t	he po	sitio	n of t	the c	orne	r;		
8- Set 5/8" X 16" rero											·						· · · ·	L. 1.
Wit: 5" Tamarack	S24	4ºE	62.7	75'											نوس	TE (	)F M/(	HIGALL
8" Cedar 8" Cedar	N4 <sup>-</sup> N08		69.5 59.9											1	75)		CARL	The state of the s
7" Cedar	N59													1	. /	×	IISKIL LAND	A By
Carsonite Pos		orth	33											1	<b>T</b>	SU	IRVEY	o <u>r</u>
Centerline of r	oad Sc	outh	5.5	±										*	بني	•.	No. 22091	* &
														.,	130	· ·	 10201	· ONCE
															115	Eg	LAN	SURFACE
	) 1		- 11	/	) .	^				_						a.k.	E BERTA	
Signed by:	Parl	_/	Ki	ab	ليك	E		Date:		7-	28	3-6	23					
Surveyor's Michigan	License N	lo.:		33981									_					