## BURVEY & REMORDINGSTATION

STATE OF MICHIGAN COUNTY OF CHARLEVOIX

SEP 1 2 1995

## LAND CORNER RECORDATION CERTIFICATE

95 AUG -4 AM 9: 18

 cornore	in	500 - 500 B	AB

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970 Located in: Corner Code ##

Charles 13. Boules REGISTER OF DEEDS

Charlevoix T 32N R 5W D-1 **Public Land Survey** T \_\_\_\_\_ R \_\_\_\_\_ \_ R . T \_\_\_\_ R \_ \_ T \_\_\_\_ R \_ **Property Controlling** S \_\_\_\_ R \_\_ in Section \_\_ T .\_\_\_ R \_ Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

\_\_ , Recorded Plat \_\_ 5. Private Claims \_\_\_

I, <u>Wayne E. Boss</u>, in a field survey on <u>May 24</u>, 19 <u>94</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12 13

Description of original monument and accessories and/or subsequent restoration:

IGLO Set 1/4 Sec Post Beech 12, N74W, 38
 Beech 6, N76E, 10 John Mullett, May 1840 Cor Fd July 1888 Survey, no reference made to stakes with mound & pits 5'. witnesses

E.K. Robinson in Sec Sub cor and NW cor. Set cedar

3. Mounds and pits 5' E

4. Mounds and pits 5' W 5. Mounds and pits 5' S E.A. Robinson, May 1906

Cor reset midway between NE T-Iron set midway between 3/4" pipe \Fd fits Feindt, wit. NE cor & NW cor 6. W 26.67', 6" Maple

7. N70°E, 15.15', 8" Maple 8. S70°E, 14.80', 7" Maple Sherman Chamberlain, Oct 1979 (Larry Feindt witnessed

Cedar Post 6. 6" Maple (cluster) S85°W, 26.60 7. 8" Maple (cluster) N55°E,

Replaced with DNR Mon &

15.07 8. 8" Maple (cluster) W85°E,

14.9 9. 2" pipe (flush w/ground)

N75°E, 26.60' Carl Roser, Jan 1982

LCRC L140. Pg. 2. Used insubsequent surveys by others

DNR Mon Fd

6. Fd 6" Maple (cluster) S84°W, 26.60

7. Fd 8" Maple (cluster) N55°E, 15.07

Fd 8" Maple (cluster) W85°E, 14.9 9. Fd 2" pipe (flush w/ground) N75°E, 26.60'

GLO to E-1 = 2640GLO to C-1 =2640

Roser 2622.75 Roser 2623.63

Charlevoix Co. Surveyor APPROVED

Signature Mary C. F. Date: July 20,1996 PA 345 of 1990

Description of monument for corner and accessories established to perpetuate locating the position of the corner: THE OF MICHIGAN

D-1 DNR Mon Fd

6. Fd 6" Maple (cluster) S84°W, 26.60

Fd 8" Maple (cluster) N55°E, 15.07
 Fd 8" Maple (cluster) W85°E, 14.9

9. Fd 2" pipe (flush w/ground) N75°E, 26.60'

careful and faithful re-establishment of the position of the original corner.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

ned by

July 28, 1995

WAYNE BOSS
PROFESSIONAL SURVEYOR
NO.
20703
LAND SURVEY
RE FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

veyor's Michigap License No.

20703 n ?

002 FAGE 386 Date