

SURVEY & REMONUMENTATION

JAN 26 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED FOR RECORD

97 DEC 16 AM 10:24

Charlene M. Cobles
REGISTER OF DEEDS

For corners in

CHARLEVOIX (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>32NR 6W</u>	<u>B-1</u>
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, ARTHUR R. RANGER, in a field survey on SEPT. 15, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:
B-1 North 1/4 corner of Sec. 6, T.32N., R.6W.
(Not an original GLO corner)
1877-E.K. Robinson surveyed along the Town line in Sec. 31, T.33N., R.6W.
1973-Charlevoix Abstract sketch along the Town line—no corner found at that time.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
B-1 North 1/4 corner of Sec. 6, T.32N., R.6W.
1997-Arthur R. Ranger found a 1/2" iron rod and witnesses; The corner was set based on single proportionate meas.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
B-1 North 1/4 corner of Sec. 6, T.32N., R.6W.
(Set a Charlevoix County Marker)
13" Basswood S14°W 29.54'
9" Basswood N24°W 30.25'
13" Cedar N04°W 25.67'
14" Basswood S11°E 37.00'

Charlevoix Co. Surveyor
APPROVED
Signature Mary C. Feendt
Date: 12/11/97

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Arthur R. Ranger Date 12/09/97
Surveyor's Michigan License No. 31601

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 29, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1998

