SURVEY & REMONUMENTATION

OCT 1 8 1996

STATE OF HICHIGAN COUNTY OF CHARLEVOIX

96 OCT 10 AM 11: 27

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 Charles B. Carles REGISTER OF DEEDS For corners in Corner Code # Located In: CHARLEVOIX (County) T 32N R 6W 1. Public Land Survey T 31N R 6W R 2. Property Controlling R In Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number _, Recorded Plat 5. Private Claims 2 3 19 95 do hereby state that under I, Arthur R. Ranger , in a field survey on May 18 . 19 95 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 4 conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and 6 or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 8 INOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 12 Description of original monument and accessories and/or subsequent restoration: D-13 1/2 corner common to Section 32, T.32N-R.6W & D-1 Section 5, T.31N-R.6W GLO 1856- E.D. Atwater set the Qr. Sec. Corner in his resurvey and witnessed: Sugar 15" N4°W 13 lks; Sugar 10" S22°W 27 lks. 1879- E.K. Robinson, surveyor found corner and bearings; He ran the N. & S. 1/4 line North. He set new witnesses also: Beech 10" S54°W 25.75 lks; Beech 12" N46°W67.875 lks. State highway dept, found a 1" iron rod 2" above ground in fence corner and witnessed: 11" Maple S10°W 15.21'; 17" Elm West 18.21'; 7" Elm North 5.64' 1987- George Avendt, Surveyor found a ¾" rod and witnessed; 18" Maple North14.80'; 4" Beech N50°E 25.15'; 14" Maple West 14.90'; Rd. centerline South 12.00' **1**994- John Ferguson, Surveyor used the corner in a survey in Antrim County to the South. ■996- Terry Brand, Surveyor used the corner in a Survey of the Township line. 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 2-13 ½ corner common to Section 32, T.32N-R.6W & D-1 Section 5, T.31N-R.6W

1995- Arthur R. Ranger, surveyor found the ¾" iron rod and witnesses by George Avendt; The corner is in line with a long established occupation line to the North, and falls 12' North of a East/West 2-track road. The old occupation surely was based on the old survey that E.K. Robinson made in 1879. That survey started at the 1/4 corner and ran North on the 1/4 line to the North line of Sec. 32. The distance East to the Sec. Corner measures approx. 2623' (GLO 2640'). Description of monument for corner and accessories established to perpetuate locating the position of the corner. 2-13 1/2 corner common to Section 32, T.32N-R.6W & D-1 Section 5, T.31N-R.6W ≡et a Harrison Monument 2" Basswood S20°W 23.92 Charleveix Co. Surveyor APPROYED ' Maple West 14.80' D" Maple North 15.16' Signaturo May C. Ternet. Date: Obbecte, 1986 Ash N77°E 25.26' tictly local in nature and is accepted as the boar available sydence of the position of the original corner. aned by ARTHUR R ∎rveyor's Michigan License No. RANGER 3160 \star 3160.

PROFESSIONAL SURVEYOR

CHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995

HRIP 003 FAGE 34