MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY BIVISION

LAND CORNER RECORD

T. 33 H.R. 4 W

			Charlevoix			COUNT
DESCRIPTION OF CORNER _	Diosing cor	ner common	to Secti	ons 4 and	l 5,	
ORNER HONUMENT Le:	t li pipe	_	north bo	undary of	townsh	Lp
ATE MONUMENT PLACED AND	WITHESSED	A ugust 1	7, 1961			
ITMESSES TO CORNER	•					··
	18" Els	*	857W	-	103.8	feet
5						
	AND					

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Foune 12" pipe at corner, as restored by Marcus Schaaf, RLS, in 1930's. Appears to be a restoration of a previous survey by county surveyor in 1909. Checks record measurements and line over corners south between 4-5 where the N1/8, the 1/4 corner and the SE corner of Section 5 can be identified as being the result of the 1909 survey.

Corner to Sections 32 and 33, T34N, R4W is 30 links east.

SURVEYOR'S SEAL

SIGNED Lemeth Delling DATE 8/18/61
REGISTERED LAND SURVEYOR

REGISTERED LAND SURVEYOR