

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 33 N.R. 4 W


Charlevoix COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 9-10-15-16

CORNER MONUMENT Left 2" pipe in place

DATE MONUMENT PLACED AND WITNESSED 8/31/61

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

8" R. Pine	-	S24E	-	62.3 feet
9" R. Pine	-	S41 $\frac{1}{2}$ W	-	41.1 feet
AND				
7" Elm	-	N67W	-	15.5 feet

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found while making a survey in this area. Found 2" pipe in N-S road, at intersection with old road grade from east. Probably as restored by Marcus Schaaf, Reg. Land Surveyor in a previous survey. Checks okay to section corner north, and considered best available evidence.

SURVEYOR'S SEAL

SIGNED Kenneth Ostling DATE 9/22/61
REGISTERED LAND SURVEYOR