

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 33 N.R. 4W
T. 33 N.R. 5W Charlevoix COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 6 - 1.

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 12-6-61

WITNESSES TO CORNER.....



4" Hemlock - S78 W - 29.5 feet

5" Elm - N 27 W - 34.4 feet

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored by single proportionate measurement between section corners while making a survey in this area. No evidence of a previous corner.

SURVEYOR'S SEAL

SIGNED *Kenneth J. Petting* DATE 12/12/61
REGISTERED LAND SURVEYOR