# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF—: | LOCATED IN—: | CORNER CODE NUMBER |
|---|---|---|
| 1. PUBLIC LAND SURVEY _____ | T. 33 N. ☐., R. 4 ☐. W. | D-10; |
| 2. PROPERTY CONTROLLING IN SECTION 29 | ,T. 33 N. ☐., R. 4 ☐. W. | 8; |
| 3. MISCELLANEOUS PROPERTY IN SECTION 29 | ,T. 33 N. ☐., R. 4 ☐. W. | 642.49'E OF C-10 |

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 6, 19 85, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on DECEMBER 6, 19 85, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. Continued

642.49' East of C-10

Drove 5/8" x 34" rerod w/RLS cap & cedar post w/loc tag

| | | |
|---|---|---|
| 6" Maple | N20°W | 10.8' |
| 15" Ash | S58°E | 8.6' |
| 5" Maple | S68°W | 6.5' |

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-10 - Restored center of Section 29 from two E.A. Robinson Bit. stump's where we also fd. top of sq. post rotted & lying on ground. See Chandler Bk., pgs. 4-9, dated Jan. 1902.

8 - Re-estab. W 1/8 cor. on E-W 1/4 line mid-way & on line bet. recovered ctr. & W 1/4 cor. of Sec. 29. Eyeball fn. intersection (fn's S&W) is S43°E, 36'+.

642.49' East of C-10 - Estab. SE Cor. of W 1/2 of SW 1/4 of NW 1/4 of Sec. 29, 642.49' east of W 1/4 Cor. of Sec 29 & on line bet. Fd. W 1/4 cor. & ctr. of Sec. 29. B-W in trees & new ced. posts to N is 10'±W. Very crooked E-W fn. (B-W in trees & some new ced. posts) is south 10'±. Old ced. post fn to east (also crooked) is 15'± south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-10

Drove 5/8" x 34" rerod w/RLS cap from fd. two EAR(1902) wit. & set ced. post w/loc tag

| | | |
|---|---|---|
| 6" Cedar | N26°E | 28.9' |
| 8" Cedar | N70°E | 62.0' |
| 9" Cedar | S26°E | 6.1' |
| 10" Cedar | S80°W | 40.7' |
| *20" Cedar stp | N14½°E | 7.1' |
| *30" Cedar stp | S17½°W | 7.6' |

*E.A. ROBINSON 1902 WIT.

8

Drove 5/8" x 34" rerod w/RLS cap & set ced post w/loc tag

| | | |
|---|---|---|
| 14" Maple | N74°W | 49.3' |
| 12" Maple | N30°W | 49.3' |
| 13" Maple | S52°E | 29.2' |

SIGNED BY Carl F. Roser 02-07-86 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET