LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N. S., R. 4 E. W.	D-6;D-5;E-5
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 4, 19 85, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (Continued):

E-5

Fd. Dept. monument and set cedar post

8"	Ash	N40°W	29.5'
10"	Ash	N18°E	5.8'
12"	Ash	S04°E	43.7'
3"	Maple	S70°W	14.6'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-6 - Restored ctr. of Sec. 17 per E.A. Robinson survey & sec. subd. of Sec. 17 dated July 1902, notes in Chandler Bk., pg. 16 at courthouse, set at intersection of 1/4 lines which also fits line across fd. E 1/8 & W 1/8 on E-W 1/4 line. Also fits E.A. Robinson tie east 62' to East edge of creek and West 16.5' to R.R. grade. Corner falls 4'± South of ctr. of E-W gravel road.

D-5 - Previous Dept. corner of record (1961). Fits E.A. Robinson survey of Sec. 17, dated July 1902; see Chandler Field Book, pg. 16 at Jury Room in courthouse.

E-5 - Previous Dept. corner of record (1961). Fits E.A. Robinson survey of Sec. 17, dated July 1902; see Chandler Field Book, pg. 16 at Jury Room in courthouse.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-6

Drove 5/8" x 34" rerod w/RLS cap

5" Maple	S34°W	60.90'
13" Tamarack stp	S38°E	47.36'
Ctr of Middle of 3-40" CMP on creek	East	50.5'
Power Pole	N74°E	150.00'
Set cedar post w/loc tag	North	33'

D-5

Fd. Dept. monument & cedar post

14" Twin Balsam stp	N08°W	16.2'
8" Balsam	S88°E	18.2'
3" Maple	S12°W	22.6'
9" Cedar	N76°W	33.4'

SIGNED BY Carl F. Roser 02-07-86 DATE _____

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET